



**Spindle Lifting Lever
for 12,7mm Range**
Item number: 21EZA198



Description

- The spindle lifting lever is attached to the top end of the spindle for improved inspection efficiency when using a dial indicator mounted on a stand.

Features

Use for:	Indicators ID-C (up to 12 mm range) ID-S, ID-SS
Functions:	Spindle lifting lever